

Allgemeine Anforderungen an die Bemusterungsunterlagen

- Bemusterungsunterlagen gemäß VDA Band 2 Vorlagestufe 2 bzw. nach Anforderungen der HWA AG.
→ etwaige Erweiterungen auf der Zeichnung / Lastenheft sind zu beachten.
- Bemusterungsunterlagen in Papierform und digital.
Vollständig ausgefüllt.
- Nachweis REACH-Konformitätserklärung.
- Abnahmeprüfzeugnis 3.1 nach EN 10204.
- DS-Merkmale sind gesondert zu prüfen / dokumentieren.
(Bsp. Rauigkeit bei Oberflächen, Berstdruck bei Drücken, ...).
- Anzahl Musterteile nach Vereinbarung mit HWA AG.
- Erstmuster sind Kennzeichnungs- und Serialisierungspflichtig.
- Dokumentationen sind bis 15 Jahre nach Produktionsende zu archivieren.

Kontaktdaten bezüglich Fragen zur Bemusterung

QM@hwaag.de

General requirements for sampling documents

- Sampling documents according to VDA volume 2 level 2 or as required by HWA AG
→any add-ons on the drawing/specifications have to be observed
- Sampling documents in paper and digital form filled in completely
- Proof of REACH Conformity declaration
- Inspection certificate 3.1 according to EN 10204
- DS features must be checked / documented separately. (e.g. surface roughness, bursting pressure,...)
- Number of sample parts (as agreed with HWA AG)
- Initial samples are required for labeling and serilization
- Documents must be archived up to 15 years after the end of production

Contact details regarding sampling questions

QM@hwaag.de